



10 Spruce Street, Paris, ON N3L 1H6
(519) 442-0499 Fax: (519) 442-6155
www.bagtexpackaging.com

Quality Assurance Program

Bag Tex Packaging's quality assurance program sets out the following procedures:



1. The final assembly person is responsible to check all components for errors made in subassembly. Once item is complete the Q.C./sewer identification tag is attached to the item.



2. A final full visual Q.C. inspection of every item produced is completed looking for missed stitches, back tacks, sewing errors as well as the trimming of all end cut threads over 1/4" in length by our Q.C. inspectors.



3. Once the visual Q.C. inspection is done, our inspectors will refer to our Q.C. log that lists items and/or areas of concern or special interest that must be checked and cross referenced with the finished product. If all items are acceptable, a serial # is issued for that bag and the Q.C. log is filled in accordingly. (The information on these forms is prepared by our designers and/or project manager).



4. Every 1st item per Q.C. log sheet is fully measured according to the report and any deviation beyond our spec is dealt with immediately. These reports are filed thereby allowing us to have total tractability of the product by its serial number.

Whether it's surface protection or part transfer, Bag Tex has it covered.

It's in the Bag!